

Inspection Photos
Location Name: Graham Unit #2
Location ID:336415



Photo 1 Access road over grown with dead weeds



Photo 2 WH

Inspection Photos
Location Name: Graham Unit #2
Location ID:336415



Photo 3 Mechanical issue and stained soil around well head



Photo 4 Debris: dead weeds on location and around electric breaker panel.