

Inspection Photos  
Operator: Logos Operating  
API#: 067-05469  
Date: 4/8/2020



Photo 1. View of the project area from the well pad entrance facing center.






Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Desirable vegetation is sparse and area is weedy. Little desirable vegetation present. Erosional rilling occurring in destabilized soils along the slope.






Photo 3. View of dense Russian thistle in the northern project area. Little desirable vegetation present.





Photo 4. View of more Russian thistle debris along the eastern edge of the working area.





Photo 5. View of reference area comprised of open pinyon-juniper woodland with sagebrush shrubland understory.