

Inspection Photos
Operator: Logos Operating
API#: 067-08088
Date: 4/8/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is in a grazed condition and comprised of western wheatgrass.



Photo 3. View of musk thistles within the interim reclamation area, approximately 50 individuals observed.



Photo 4. View of reference area, comprised of irrigated grass field in a grazed condition.