

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2020

Submitted Date:

04/13/2020

Document Number:

689704558

FIELD INSPECTION FORM

Loc ID 334903 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259463	WELL	PR	03/06/2001	GW	045-07731	BARRETT GM 241-1	PR
275734	WELL	PR	08/29/2005	GW	045-10380	WILLIAMS GM 421-1	PR
275735	WELL	PR	08/29/2005	GW	045-10381	WILLIAMS GM 332-1	PR
275736	WELL	PR	08/29/2005	GW	045-10382	WILLIAMS GM 521-1	PR

General Comment:

[Follow Up Field inspection](#)
On Friday 04/10/2020 at approximately 1200 hours, I, Inspector Mike Longworth, conducted a follow up field inspection at Terra Rocky Mountain LLC WILLIAMS-67S96W NENW, at Location # 334903 in Garfield County, Colorado
All corrective actions have been addressed from 02/21/2020 Inspection # 689704236

Inspected Facilities									
Facility ID:	<u>259463</u>	Type:	<u>WELL</u>	API Number:	<u>045-07731</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>							Date:	
Corrective Action:								Date:	
Facility ID:	<u>275734</u>	Type:	<u>WELL</u>	API Number:	<u>045-10380</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>							Date:	
Corrective Action:								Date:	
Facility ID:	<u>275735</u>	Type:	<u>WELL</u>	API Number:	<u>045-10381</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>							Date:	
Corrective Action:								Date:	
Facility ID:	<u>275736</u>	Type:	<u>WELL</u>	API Number:	<u>045-10382</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>							Date:	
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			

Comment: [Road ditch has been maintained.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704563	Inspection 689704558 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5121773