

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/13/2020

Submitted Date:

04/13/2020

Document Number:

696301671

FIELD INSPECTION FORM
 Loc ID 326976 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 88380

Name of Operator: TINDALL OPERATING COMPANY

Address: P.O. BOX 4507

City: ENGLEWOOD State: CO Zip: 80155

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Witzel, Carrie	(303) 825-8956	dnroilgas@hotmail.com	All Inspections
Simms, John	(303) 825-8956	dnroilgas@hotmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246165	WELL	SI	05/01/2019	GW	123-13962	NICKERSON 4	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil at Engine, see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."	Date:	11/01/2019
Type	TRASH		
Comment:	Trash on the Northeast side of pumping unit. See photo		
Corrective Action:	Comply with Rule 603.f.	Date:	11/01/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused Pumping Unit and engine, engine housing, 4 deadman anchors, multiple chemical tanks, propane tank (500 gallons). Separator and Crude Oil Tank, and Stairs See photos		
Corrective Action:	Comply with Rule 603.f.	Date:	12/02/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Chemical Tanks and Containment		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.576960,-103.916450	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No					
Comment:					
Corrective Action:				Date:	

Flaring:

Type				
Comment:				
Corrective Action:				Date:

Inspected FacilitiesFacility ID: 246165 Type: WELL API Number: 123-13962 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Well has been Plugged and Abandoned.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass	Seeding	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID:

Lat: 40.576696Long: -103.916270Reference Point: SE

Other: _____

Length: 15Width: 10**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date: 08/28/2018

Gaps observed under mesh / frame pit covering on multiple sides. Maintain net or fence pit to prevent access per Rule 902.d.
 Comply w/ Rule 902.d.
 Original Corrective Action Date: 08/28/2018, remains applicable.

Maintain net or fence pit to prevent access per Rule 902.d.
 Comply w/ Rule 902.d.
 Original Corrective Action Date: 08/28/2018, remains applicable.

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 04/08/2020 at approximately 11:22, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Tindall Operating Company, Nickerson #4 at Location #326976 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>The open Well Bore has been Cut and Capped. No further action at this time.</p> <p>Trash is still in the Northeast side of the Pumping Unit, see photos. Comply with Rule 603.f. Corrective Action Date 11/01/2019.</p> <p>Stained Soil at Engine, see photos. Comply with Rule 603.f. Corrective Action Date 11/01/2019.</p> <p>Multiple Unused Equipment: Pumping Unit, Horse's Head, Wellhead parts and fittings, Engine, Engine Shed, Chemical Tanks/Pumps, Propane Tank, Separator and Crude Oil Tank. See photos. Comply with Rule 603.f. Corrective Action Date 12/02/2019.</p> <p>Gaps observed under mesh / frame pit covering on multiple sides. Maintain net or fence pit to prevent access per Rule 902.d.</p> <p>Original Corrective Action Date: 08/28/2018, remains applicable.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report.</p>	petrie	04/13/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301672	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5121956