

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402366020

Date Received:

04/08/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Mack, Ronald

ronaldmack@tcenergyllc.com

BAKER DAVID

dbaker@auroramp.com

Fitzgerald, Edie

ediefitzgerald@tcenergyllc.com

Dylan Thomsen

timothy.thomsen@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901939

Inspection Date: 03/19/2020

FIR Submit Date: 03/20/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309235

Location Name: GOLDEN EAGLE-633S67W Number: 31SENW County: LAS ANIMAS

Qtrqtr: SENW Sec: 31 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.128790 Longitude: -104.930434

FACILITY - API Number: 05-071- -00 Facility ID: 290523

Facility Name: GOLDEN EAGLE Number: 31-6

Qtrqtr: SENW Sec: 31 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.128790 Longitude: -104.930434

CORRECTIVE ACTIONS:

1 ☒ CA# 137353

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C
Implement or modify BMPs for improved material handling and spill prevention.
Immediately clean up area.

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/07/2020

Operator
Comment:

The oily waste was removed from the PC engine skid and the liquid ring compressor skid immediately. The impacted soil around the liquid ring was removed from location. The maintenance to the liquid ring compressor was completed 04/07/20. The lease road was regraded to eliminate the surface erosion and establish sheet flow. The bar ditch was dominated to direct run off to the culvert inlets. The sediment was removed from the culvert inlet. The erosion rill on the fill slope was back filled and seeded by hand broadcast with an approved CPW seed mix.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 4/8/2020 6:45:34 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402366020	FIR RESOLUTION SUBMITTED
402366023	Photo Log

Total Attach: 2 Files