

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402369040

Date Received:

04/13/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

BAKER DAVID

dbaker@auroramp.com

Dylan Thomsen

timothy.thomsen@state.co.us

Fitzgerald, Edie

ediefitzgerald@tcenergyllc.com

Mack, Ronald

ronaldmack@tcenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901927

Inspection Date: 03/19/2020

FIR Submit Date: 03/20/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 422360

Location Name: GOLDEN EAGLE Number: 30-08 County: LAS ANIMAS

Qtrqr: SENE Sec: 30 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.144700 Longitude: -104.922116

FACILITY - API Number: 05-071- -00 Facility ID: 422353

Facility Name: GOLDEN EAGLE Number: 30-08

Qtrqr: SENE Sec: 30 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.144700 Longitude: -104.922116

CORRECTIVE ACTIONS:

1 ☒ CA# 137336

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/10/2020

Operator Comment: A dirt berm was installed around the 200 BBL above ground water storage tank.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 137337

Corrective Action: Repair and maintain lease road.

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/10/2020

Operator Comment: The lease road was regraded to eliminate the tire ruts and establish sheet flow.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

3 ☒ CA# 137338

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/10/2020

Operator Comment: The deteriorated muffler on the liquid ring compressor was replaced and all valves, pipes and fittings were securely fastened to maintain good mechanical condition.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

4 ☒ CA# 137339

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/10/2020

Operator Comment: The sediment was removed from the culvert inlet. The access road was regraded to eliminate the potholes. The bar ditch was dominated to direct run off to the culvert inlet.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed. See attached photo log for details.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 4/13/2020 12:40:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402369040	FIR RESOLUTION SUBMITTED
402369059	Photo Log

Total Attach: 2 Files