

Inspection Photos
Location Name: Kelsall 33-7 #4-4
API: 05-067-09880



Kelsall 33-7 #4-4 location photo.



Overright Trucking water hauler on location during this inspection.

Inspection Photos
Location Name: Kelsall 33-7 #4-4
API: 05-067-09880



Wet and stained soil and gravel around #4-4 well head.



Stained soil near prime mover exhaust for #4-2.

Inspection Photos
Location Name: Kelsall 33-7 #4-4
API: 05-067-09880



Stained soil on pallet near #4-2 pump jack.



Stained well head and surroundings at #4-1.

Inspection Photos
Location Name: Kellsall 33-7 #4-4
API: 05-067-09880



Stained soil at prime mover exhaust for the #4-1.



Unused lube oil container at #4-4.

Inspection Photos
Location Name: Kelsall 33-7 #4-4
API: 05-067-09880



Wet and stained gravel near the #4-4.



Previous operator listed on tank label.

Inspection Photos
Location Name: Kelsall 33-7 #4-4
API: 05-067-09880



Tank battery sign mounted to stairway railing.



Produced water spilled while disconnecting transfer hose.

Inspection Photos
Location Name: Kelsall 33-7 #4-4
API: 05-067-09880



Hose stored in secondary containment for tank battery.



Domestic tap #463853.