

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/14/2020

Submitted Date:

04/14/2020

Document Number:

696301687

FIELD INSPECTION FORM

Loc ID 305168 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 70385
Name of Operator: SMITH ENERGY CORP
Address: 12706 SHILOH RD
City: GREELEY State: CO Zip: 80631

Findings:

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Glenn	(970) 330-7034	gsmithten@what-wire.com	
Smith, Chris	(970) 330-7034	smithenergy@live.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274861	WELL	SI	06/01/2018	OW	123-22590	CHINOOK 1	SI

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unmarked Riser at Gas meter, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	04/17/2020
Type	WEEDS		
Comment:	New weed encroachment observed around entire tank battery, wellhead, location & access road areas. Original Corrective Action Date still applies: 06/20/2019 Refer to Rule 603.f. See photos		
Corrective Action:	Remove, manage, & control weeds around entire tank battery, wellhead, location & access road areas. Comply with Rule 603.f. See photos	Date:	06/20/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Deadman # & Marked	#		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	Does not appear to be plumbed to surface		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV STEEL		
Comment:					Date:
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Share berm with the Maintenance Tank			Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.579250,-103.732090
Comment:	Maintenance Tank				Date:
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

Venting:

Yes/No		Date:
Comment:		
Corrective Action:		

Flaring:

Type	
------	--

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 274861 Type: WELL API Number: 123-22590 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI. Observed production valves closed.
COGCC records indicate last prod: 05/2018.
Well is approaching the 2-Year Shut-In MIT per Rule 326.b.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding		Seeding				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 04/08/2020 at approximately 13:54, I, Inspector Erica Petrie, conducted a Field Inspection at Smith Energy Corp. Chinook #1 at Location #305168 in Weld County, Colorado. While there, I observed Production Operations During this inspection the following possible compliance issues were observed: 1 of 1 Corrective Actions appears NOT addressed. 1 new Corrective Action 1.) Weed encroachment observed around entire wellsite. Refer to Rule 603.f. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 06/20/2018. See photos. 2.) Unmarked Riser at Gas Meter, see photos. Comply with Rule 603.f. Corrective Action date: 04/17/2020. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petrie	04/14/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301688	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5123570