

Inspection Photos

4/09/2020

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 448472

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 1: Photo taken from the southern end of the Location, facing southwest. Photos 1-4 provide an overview of the Location from southwest, west, northwest, to north. Photos show large areas of the Location that are not needed for production activities have not been reclaimed in accordance with 1003 rules.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 5: Photo taken from the southeast corner of the Location, facing north. Photos 5-7 provide an overview of the Location. Photos show large areas of the Location that are not needed for production activities have not been reclaimed in accordance with 1003 rules.

Photo also shows the topsoil stopckpile on the southwest end of the Location. Operator appears to have tracked drill cutting onto the soil stockpile.



Photo 6: See comments under photo 5.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 7: See comments under photo 5.



Photo 8: Photo taken from the west end of the Location. Doc. #401115672 identifies this soil stockpile as the “Topsoil Stockpile” that was salvaged from the Location during construction operations. Document #402174440 under sundry doc. #402163224 shows the topsoil pile was to be used for cuttings placement; Operator appears to have placed the drill cuttings upon the Topsoil stockpile in violation of Rule 1002.b(2) and 1002.c

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 9: See comments under photo 8. Note- White material (arrow) observed on tracked soils (drill cuttings) in photo is not snow.



Photo 10: Photo taken from the topsoil stockpile on the west end of the Location, facing northwest. Photos 10-14 provide an overview of the Location from north, northeast, east, southeast to south. Photos show overview of the Location, including areas that are not needed for production activities have not been reclaimed in accordance with 1003 rules. Photos also shows areas where drill cuttings were placed and tracked upon the topsoil stockpile.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 11: See comments under photo 10.



Photo 12: See comments under photo 10.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 13: See comments under photo 10.



Photo 14: See comments under photo 10.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 15: Photo taken from the northwest end of the Location, facing north. Photo shows areas of the Location not needed for production activities have not been reclaimed. Photo also shows areas where drill cutting are being stored.



Photo 16: Photo taken from the northwest end of the Location, facing northeast. See comments under photo 15.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 17: Photo taken from the northern corner of the Location, facing southeast. Photo shows areas where Operator appears to have pushed drill cuttings onto the perimeter of the Location, and on onto areas designated as topsoil (Doc. #401115667). It was observed that no additional BMPs have been installed to prevent cuttings from being transported/discharged off the Location onto the adjacent lands.



Photo 18: Photo taken from the northern corner of the Location, facing southwest. See comments under photo 17.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 19: Photo taken from the northern corner of the Location, facing southeast. Photo shows areas where Operator appears to have pushed drill cuttings onto the perimeter of the Location, and on onto areas designated as topsoil (Doc. #401115667). It was observed that no additional BMPs have been installed to prevent cuttings from being transported/discharged off the Location onto the adjacent lands.



Photo 20: Photo taken from the northeastern area of the Location, facing northwest. See comments under photo 19.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 21: Photo taken from the north end of the Location, facing north. Photo shows unused equipment and/or trash debris stored on the Location.



Photo 22: Photo taken from the east of the tank battery, facing west. Photo shows unused equipment and/or trash debris stored on the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 23: Photo of diesel tank stored to the east of the battery. If tank is not needed for production activities, it needs to be removed per Rule 603.f. Secondary containment at tank appears to be in proper functioning condition.



Photo 24: Photo taken of tank battery on the north end of the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 25: Photo taken from the central area of the Location, facing southwest. Photo shows separators on the Location.



Photo 26: Photo of methanol tanks south of the wells.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 27: See comments under photo 25.



Photo 28: Photo taken from the south of the separators.
Photo shows pipe equipment/trash debris stored on location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 29: Photo taken from the south end of the location, facing southeast. Photo shows rock material stored on the location.



Photo 30: Photo taken from the eastern area of the location, facing northeast. Photo shows rock material stored on the location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 31: Photo taken from the east end of the Location, facing east. Photo shows trash debris that appears to be related to a hose (arrow, see photo 32). Trash debris and unused equipment requires removal in accordance with 603.f and 1003.a



Photo 32: See comments under photo 30.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 448472



Photo 33: Photo taken from the east end of the Location, facing south. Photo shows trash debris on the Location.