

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /35SENW

Location ID: 312511



Network time is not synchronize
Local: Apr 14, 2020 at 11:30:12 AM MD
+39.1517, -108.145



Network time is not synchronize
Local: Apr 14, 2020 at 11:38:00 AM MD
+39.3170, -108.299

Photo #0961 from entrance to location

Photo #0962 Debris inside both pits. No netting on pits.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /35SENW

Location ID: 312511



Photo #0963 Debris inside both pits. No netting on pits.



Photo #0964 Multiple flowline risers not LO/TO.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /35SENW

Location ID: 312511



Photo #0965 Multiple flowline risers not LO/TO.