

Inspection Photos

Operator: Enduring Resources
API#: 067-07914
Date: 4/14/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Revegetation is progressing here with grasses and shrubs such as western wheatgrass, sand dropseed, and rubber rabbitbrush.



Photo 3. View of dense musk thistles within the southwestern portion of the project area.



Photo 4. View of reference area, comprised of pinyon-juniper woodland with understory of sagebrush and grasses and forbs such as blue grama and snakeweed.