

**Inspection Photos**  
**Operator: Enduring Resources**  
**API#: 067-06692**  
**Date: 4/14/2020**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Revegetation is progressing here with grasses and shrubs such as western wheatgrass, and smooth brome.



Photo 3/4. View of rubber hose at access gate and plastic debris within the interim reclamation area.



Photo 5. View of reference area, comprised of pinyon-juniper woodland with understory of sagebrush and grasses and forbs such as blue grama and snakeweed.