

**Inspection Photos**  
**Operator: Enduring Resources**  
**API#: 067-08658**  
**Date: 4/14/2020**



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southern corner facing westward. Revegetation is with rubber rabbitbrush and western wheatgrass. Interim reclamation area, is largely rock fill.



Photo 3. View of the eastern fill slope from the southeastern corner facing northward.



Photo 4. View of reference area, comprised of pinyon-juniper woodland with understory of sagebrush, antelope bitterbrush, and a mixture of grasses and forbs.