

Inspection Photos
Operator: Enduring Resources
API#: 067-07636
Date: 4/14/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northeastern fill slope from the northern corner facing southeastward. Revegetation is progressing, largely with western wheatgrass and sand dropseed.



Photo 3. View of reference area, comprised of pinyon-juniper woodland with understory of sagebrush, antelope bitterbrush, and a mixture of grasses and forbs.