

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2020

Submitted Date:

04/16/2020

Document Number:

688307641

**FIELD INSPECTION FORM**

Loc ID: 322209 Inspector Name: Sherman, Susan On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10646  
Name of Operator: AXIS EXPLORATION LLC  
Address: 370 17TH ST SUITE 5300  
City: DENVER State: CO Zip: 80202

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Chesson, Robert		robert.chesson@state.co.us	COGCC EPS
Dunning, Michael	303 396-6040	mdunning@extractionog.com	
Antonioli, Philip	720-345-4603	PAntonioli@extractionog.com	
Extraction	720-370-5540	COGCCInspections@extracti onog.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209725	WELL	SI	04/01/2018	GW	039-06630	HSR-WHITEHEAD 14-9	PA

**General Comment:**

Followup PA Inspection

Inspector observed an open excavation, inside fencing, at the location of the fiberglass produced water tank after PA (see attached photo). No odors smelled at excavation. Gas meter was fenced (in pasture). A Form 191 has been submitted to COGCC database.

Well not cut, capped or covered yet.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type OTHER

Comment: gas meter run

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

Type	#	corrective date
Flow Line	# 1	
Comment:		
Corrective Action:		Date: _____
Pump Jack	# 1	
Comment:		
Corrective Action:		Date: _____
Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date: _____

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:	sitting empty on side of tank battery location				
Corrective Action:					Date: _____

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	<input type="text"/>			

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 209725 Type: WELL API Number: 039-06630 Status: SI Insp. Status: PA

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688307654	Axis Exploration LLC, HSR-Whitehead 14-9	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5126117">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5126117</a>