

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402373624

Date Received:
04/17/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Dylan Thomsen</u>		<u>timothy.thomsen@state.co.us</u>
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>
<u>Baker, David</u>		<u>dbaker@auroramp.com</u>
<u>Fitzgerald, Edie</u>		<u>ediefitzgerald@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901923
Inspection Date: 03/19/2020 FIR Submit Date: 03/20/2020 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309119

Location Name: GOLDEN EAGLE-633S67W Number: 31NWNE County: LAS ANIMAS
Qtrqr: NWNE Sec: 31 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.133790 Longitude: -104.926200

FACILITY - API Number: 05-071-00 Facility ID: 288302

Facility Name: GOLDEN EAGLE Number: 31-2
Qtrqr: NWNE Sec: 31 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.133790 Longitude: -104.926200

CORRECTIVE ACTIONS:

1 CA# 137333

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/16/2020

Operator Comment: The access road was regraded to eliminate the tire ruts and establish sheet flow. The sediment was removed from the culvert inlet. A water turnout was installed to direct run off away from the access road toward the undisturbed natural vegetation. The ditch scouring was corrected by back filling the ditch and compacting the soil with the tire of the backhoe. Rock sock checks were installed in the bar ditch to filter sediment. The impacted soil on the well pad was removed from location. See photo attachment for details.

COGCC Decision: _____

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 4/17/2020 9:01:50 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402373643	Photo Log
-----------	-----------

Total Attach: 1 Files