

GOLDEN EAGLE 31-02 API# 05-071-09108 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901923



PHOTO 1: THE ACCESS ROAD TO LOCATION WAS SURFACE CROWNED TO ESTABLISH SHEET FLOW AND ELIMINATE THE TIRE RUTS. A WATER TURNOUT WAS INSTALLED TO DIVERT RUN OFF AWAY FROM THE ACCESS ROAD TO UNDISTURBED NATURAL VEGETATION. ROCK SOCK CHECKS WERE PLACED IN THE DITCH LINE FOR SEDIMENT CONTROL.



GOLDEN EAGLE 31-02 API# 05-071-09108 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901923



PHOTO 2: THE ACCESS ROAD TO LOCATION WAS SURFACE CROWNED TO ESTABLISH SHEET FLOW AND ELIMINATE THE TIRE RUTS. ROCK SOCK CHECKS WERE PLACED IN THE DITCH LINE FOR SEDIMENT CONTROL.



GOLDEN EAGLE 31-02 API# 05-071-09108 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901923



PHOTO 3: THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET ALONG THE ACCESS ROAD.



GOLDEN EAGLE 31-02 API# 05-071-09108 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901923



PHOTO 4: THE BAR DITCH WAS BACK FILLED AND THE SOIL WAS COMPACTED WITH THE BACK HOE TIRE TO ELIMINATED THE DITCH CUTTING ALONG THE MAIN ROAD. ROCK SOCK CHECKS WERE PLACED IN THE DITCH LINE FOR SEDIMENT CONTROL.

GOLDEN EAGLE 31-02 API# 05-071-09108 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901923



PHOTO 5: THE STAINS ON THE WELL PAD WAS CLEANED UP.