

Inspection Photos

API: 071-09853

Operator: TIMBER CREEK OPERATING

Inspection Date: 4/15/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 4/15/2020

Inspection Photos



Photo 1. The culvert along the main lease road has been maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 4/15/2020

Inspection Photos



Photo 2. Facing northwest along the main lease road ascending the hill. The road has been regraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 4/15/2020

Inspection Photos



Photo 3. The culvert along the main lease road has been maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 4/15/2020

Inspection Photos



Photo 4. A berm has been installed around the open topped tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 4/15/2020

Inspection Photos



Photo 5. The exhaust pipe which was laying on the ground has been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 4/15/2020

Inspection Photos



Photo 6. Facing east toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 4/15/2020