

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402373624

Date Received:

04/17/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Dylan Thomsen

timothy.thomsen@state.co.us

Mack, Ronald

ronaldmack@tcenergyllc.com

Baker, David

dbaker@auroramp.com

Fitzgerald, Edie

ediefitzgerald@tcenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901923

Inspection Date: 03/19/2020

FIR Submit Date: 03/20/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309119

Location Name: GOLDEN EAGLE-633S67W Number: 31NWN County: LAS ANIMAS

Qtrqr: NWNE Sec: 31 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.133790 Longitude: -104.926200

FACILITY - API Number: 05-071- -00 Facility ID: 288302

Facility Name: GOLDEN EAGLE Number: 31-2

Qtrqr: NWNE Sec: 31 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.133790 Longitude: -104.926200

CORRECTIVE ACTIONS:

1 ☒ CA# 137333

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/16/2020

Operator Comment: The access road was regraded to eliminate the tire ruts and establish sheet flow. The sediment was removed from the culvert inlet. A water turnout was installed to direct run off away from the access road toward the undisturbed natural vegetation. The ditch scouring was corrected by back filling the ditch and compacting the soil with the tire of the backhoe. Rock sock checks were installed in the bar ditch to filter sediment. The impacted soil on the well pad was removed from location. See photo attachment for details.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 4/17/2020 9:01:50 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402373624	FIR RESOLUTION SUBMITTED
402373643	Photo Log

Total Attach: 2 Files