

# Inspection Photos

Operator: Enduring Resources  
API#: 067-08647  
Date: 4/14/2020



Photo 1. View of the project area from the northeastern corner facing center.





Photo 2. View of the northwestern project area facing southward. Cut-slopes appear to be re-seeded, hydromulch remains on slope.





Photo 3. Birdseye view of young grasses observed within revegetation area.





Photo 4. View of the eastern fill slope from the northeastern corner facing southward.



Photo 5. View of reference area, comprised of pinyon-juniper woodland with understory of sagebrush, antelope bitterbrush, and a mixture of grasses and forbs.