

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/16/2020

Submitted Date:

04/20/2020

Document Number:

688800724

FIELD INSPECTION FORM

 Loc ID 333700 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Shorty, Priscilla		pshorty@hilcorp.com	All SW Inspections
Ray, Mandy	(505) 599-4083	mray@hilcorp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258252	WELL	PR	05/09/2001	GW	067-08341	SCHIRARD 3-12U	EI
286247	WELL	PR	10/01/2009	GW	067-09232	SCHIRARD 4-12U	EI

General Comment:

On April 16, 2020 SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Schirard #4-12U. For the most recent field inspection report of this facility, please refer to document #685304397.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Sign mounted to fencing is labeled with contents and NFPA placard.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Free standing signs near location entrance.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	Posted on location signs.	
Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Guard fencing.		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Fencing around perimeter of produced water vessel.		
Corrective Action:			Date:

Equipment:				corrective date
Type: Compressor	# 1			
Comment:	Within steel building			
Corrective Action:				Date:
Type: Prime Mover	# 2			
Comment:	Electric motors			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Electrical supply panel			
Corrective Action:				Date:

Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment		
Corrective Action:			Date:
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		37.206528,-107.662986
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	120 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Produced water vessel is in below ground metal cellar.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 258252 Type: WELL API Number: 067-08341 Status: PR Insp. Status: EI

Facility ID: 286247 Type: WELL API Number: 067-09232 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass	Gravel	Pass			
Gravel	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Drip pot on load out valve.

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On April 16, 2020 SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Schirard #4-12U. For the most recent field inspection report of this facility, please refer to document #685304397. Kelley Oilfield Services was on site working on the separator for the #4-12U at the time of this inspection. This site visit was in response to Complaint #200448862. After this inspection, as well as an environmental and engineering desktop review, it does not appear that any activities on this location have affected the domestic water well.	hughesjo	04/20/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800725	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5127899