

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/16/2020

Submitted Date:

04/20/2020

Document Number:

688800727**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre		sabre.beebe@bpx.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
475421	SPILL OR RELEASE	AC	04/14/2020		-	McCarville Waterline	EI

**General Comment:**

On April 16, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP McCarville Waterline Spill/Release Point ID #475421. For more information regarding this release, please refer to document #402370031.

Inspected Facilities									
Facility ID:	475421	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

--

**Environmental****Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 23

Comment: [For more information regarding this release, please refer to document #402370031.](#)Corrective Action: [Control and contain spills/releases and clean up per Rule 906.a.](#)

Date: 05/20/2020

Reportable: YES

GPS: Lat 37.106631

Long -107.801553

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat

Long

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
On April 16, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP McCarville Waterline Spill/Release Point ID #475421. For more information regarding this release, please refer to document #402370031. A Crossfire representative was on site during this inspection. The BP poly gathering line had been hydro excavated along with two Catamount pipelines, one poly and one steel. The hydro-vac crew was potholing the Catamount lines during this inspection. The excavated area was approximately 4' by 10', and the BP gathering line appeared to be 6-7' feet bgs.	hughesjo	04/20/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800728	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5128052">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5128052</a>