

**Inspection Photos**  
**Location Name: Emerald C-1 HZ**  
**Location ID: 316328**  
**Inspection Date: April 9, 2020**



**Location sign.**



**Tank battery.**



**Inspection Photos**  
**Location Name: Emerald C-1 HZ**  
**Location ID: 316328**  
**Inspection Date: April 9, 2020**



**View of the tank battery from the excavation.**



**Excavation, repaired flowline and electrical conduit.**



## Inspection Photos

Location Name: Emerald C-1 HZ

Location ID: 316328

Inspection Date: April 9, 2020



Excavation, impacted material from the excavation, repaired flowline and electrical conduit.



Cut out section of the flowline that failed the pressure test.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Emerald C-1 HZ**  
**Location ID: 316328**  
**Inspection Date: April 9, 2020**



**Pressure testing the repaired flowline with water.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources