

Inspection Photos
Operator: Kinder Morgan
API#: 033-06184
Date: 4/14/2020



Photo 1. View of the project area from the southeastern corner facing center. Interim reclamation is not conducted.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing with young grasses such as squirreltail and Indian ricegrass.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of course rock run-down at well pad entrance appears to be functioning at this time.



Photo 5. View of reference area, comprised of gambel oak and black sage shrubland with scattered ponderosa pine trees and grasses such as western wheatgrass and squirreltail in the understory.