

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Plunger Lift	# 1				
Type: Horizontal Heated Separator	# 1				
Type: Gas Meter Run	# 1				
Type: Vertical Separator	# 1				
Type: Bradenhead	# 1				

Tanks and Birms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Birms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		shares containment with oil tank				Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	300 BBLs	STEEL AST		,		
Comment:						Date:	
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:						Date:	
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:						Date:	
Corrective Action:						Date:	
Flaring:							
Type							
Comment:						Date:	
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 242618 Type: WELL API Number: 123-10409 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection perception of location may have been distorted due to weather conditions.	medinaj	04/21/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501111	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5128799