

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2020

Submitted Date:

04/21/2020

Document Number:

694500186

FIELD INSPECTION FORMLoc ID 324670 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knop, Max	303-825-4822	MKnop@kpk.com	
Waldron, Emily		emily.waldron@state.co.us	
		cogcc@kpk.com	All Inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212368	WELL	PR	01/01/2019	OW	057-06261	CONOCO FEDERAL 34 1	EI

General Comment:

On 4/10/2020 COGCC Staff, Kris Neidel inspected the KPK, Conoco Federal 34-1 well pad and access road. Weather was 55 degrees and dry. COGCC Environmental Staff was doing a follow up inspection to #689803959 from 4/8/2020. It was observed that the well was not pumping at the time of inspection. It appeared that a 12x20 area adjacent to the access road had been recently disturbed with a Backhoe. Approximately 100 feet to the northwest of the disturbance, there was observable weathered hydrocarbon present in the weeds. The hydrocarbon was observable on the ground and in the vegetation. The remaining hydrocarbon is spread out sparsely in an area approximately 20'x75'. This area was discussed with the operator on 4/14/20. It was stated that the area near the road was part of an attempted repair of an injection line. The remaining hydrocarbon was from a production line that failed in 2018 under the previous operator. A Form 27 remediation workplan should be submitted to document the removal of E&P waste for the oil spill. The Injection line repair should be documented on a Sundry for COGCC Integrity Group's review. See attached Photos.

Inspected FacilitiesFacility ID: 212368 Type: WELL API Number: 057-06261 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500188	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5129087