

Inspection Photos  
Operator: Kinder Morgan  
API#: 033-06135  
Date: 4/14/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern fill slope from the southwestern corner facing eastward. Revegetation is progressing with young grasses such as crested wheatgrass, intermediate wheatgrass, and western wheatgrass.



Photo 3. View of the western fill slope from the northwestern edge facing southward.



Photo 4. View of project disturbance within the southern project area. Revegetation is required when work is completed here.



Photo 5. View of reference area, comprised of open grass field similar to interim reclamation area.