

KP Kauffman - COGCC Inspection Photos
Location: Nessu Consolidated Flowline Release
Spill ID # 470915 Date 4/20/2020



View from Nessu facility (ID #453316) towards excavation at Spill ID #470915 (looking West)



Closer view of excavation at Spill ID # 470915 with flowlines exposed (looking West)

KP Kauffman - COGCC Inspection Photos
Location: Nessu Consolidated Flowline Release
Spill ID # 470915 Date 4/20/2020



View of flowlines exposed; repair work appears to be in progress (looking North)



View of excavation and flowlines exposed (to east)

KP Kauffman - COGCC Inspection Photos
Location: Nessu Consolidated Flowline Release
Spill ID # 470915 Date 4/20/2020



**View of Nessu #1 wellhead (API 123-07762);
OOSLAT (flowline shut in/ tagged out)**



**View of Nessu #2 wellhead (API 123-08811);
OOSLAT (flowline shut in/ tagged out)**