

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402369442

Date Received:  
04/13/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
.		<u>SanJuanCOGCC@bp.com</u>
<u>Beebe, Sabre</u>		<u>sabre.beebe@bpx.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901076  
Inspection Date: 11/06/2019 FIR Submit Date: 11/13/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326610

Location Name: SOWER FEDERAL GAS UNIT-N35N7W Number: 34NESW County: LA PLATA  
Qtrqr: NESW Sec: 34 Twp: 35N Range: 7W Meridian: N  
Latitude: 37.254922 Longitude: -107.627239

FACILITY - API Number: 05-067-00 Facility ID: 258938

Facility Name: SOWER FEDERAL Number: 2  
Qtrqr: NESW Sec: 34 Twp: 35N Range: 7W Meridian: N  
Latitude: 37.254922 Longitude: -107.627239

CORRECTIVE ACTIIONS:

1  CA# 134486

Corrective Action: Stormwater and erosion controls are needed to stabilize erosion on the well pad cut-slope. Stormwater controls need to be selected, sized, installed, and maintained using good engineering practices such as those described in CDOT manuals for erosion control. These controls need to be maintained in good condition until interim reclamation areas are stabilized with desirable perennial vegetation.

Date: 11/29/2019

Response: CA COMPLETED Date of Completion: 04/10/2020

Barren areas seeded and hydromulched. Erosion blanket was unable to be used as the staples would not

Operator Comment: penetrate the rock running ~2 inches below the surface. Soils on slope is only approximately 2 inches deep and not enough to stabilize the erosion blanket.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Specialist

Date: 4/13/2020 2:42:48 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402369442	FIR RESOLUTION SUBMITTED
402369447	Work completion photos

Total Attach: 2 Files