

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2020

Submitted Date:

04/22/2020

Document Number:

694500189**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
NEIDEL, KRIS 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	All Inspections
Knop, Max	303-825-4822	MKnop@kpk.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
473059	SPILL OR RELEASE	AC	03/10/2020		-	Dwinell Tank Battery	EI

General Comment:

On 4/10/2020 COGCC Staff, Kris Neidel inspected Dwinell Tank Battery spill number 473059. Weather was 55 degrees and dry. COGCC Environmental Staff was doing a follow up inspection to Spill 473059 and Remediation number 15326. At the Tank Battery, the following was observed; it was obvious that soil had been removed from the floor of the tank battery, soil was removed from along the edge of tanks, hydrocarbon impacted soil is still present below the tanks that over-topped, the spill path away from below the tanks has been scraped up, soil that was impacted from the spill and migrated to the lower secondary containment had been scraped up, a pile of impacted soil that was estimated to be 20x40x3 is stockpiled in the lower secondary containment, COGCC was notified that the soil is being hauled off for disposal at a commercial facility. The separation equipment was observed, some trash and stored equipment was observed. KPK should removed all impacted soil in the tank battery. Documentation of the Tank battery and removal of soil should be documented in REM project 15326. Trash and unused equipment observed should be removed in 90 days. See attached photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	observed in tank battery separation equipment.		
Corrective Action:	Remove equipment not necessary for production.	Date:	07/23/2020
Type	TRASH		
Comment:	observed in tank battery at separation equipment.		
Corrective Action:	Remove trash	Date:	07/23/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 473059 Type: SPILL OR API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500191	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5130149