

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2020

Submitted Date:

04/22/2020

Document Number:

699301502

**FIELD INSPECTION FORM**

Loc ID 305090 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274043	WELL	TA	02/26/2019	GW	123-22431	PARAGON FARMS 42-25	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	AG fence		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	AG fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	barbless wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barbless wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 2		
Comment:	Automation		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:			Date:	
Corrective Action:			Date:	
Type: Emission Control Device	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Pig Station	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment: exposed at surface			Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:			Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <a href="#">Shares containment with crude tank</a>				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 274043 Type: WELL API Number: 123-22431 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: TA since 2-26-2019 for HZ prep

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

## Comment

COGCC Inspection Report Summary  
 On Wednesday 04/22/2020 at approximately 1300 hrs. I, Inspector Robbie Revas,  
 Conducted an on-site inspection at a Kerr McGee location:

Paragon Farms 42-25 at APU #05-

123-22431 in Weld County Colorado.  
 While there, I observed a TA Wellsite and tank battery. TA since 2-26-2019 for HZ prep.  
 Form 04 (TA) Doc # 402306422 submitted on 2-7-2020.  
 Form 42 (MIT) Doc # 401931100 Submitted 2-6-2019  
 During this inspection no compliance issue was observed:  
 See attached photos.  
 Location is dry, weather is clear.  
 A follow up on this site inspection needs to be conducted to ensure the  
 Compliance issues have been corrected to comply with COGCC rules.  
 Continuing education COGCC Inspection Report Summary.  
 This is a summary of inspection report.

## User

revasr

## Date

04/22/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301503	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5130175">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5130175</a>