

Inspection Photos

API: 055-06287

Operator: TABULA RASA ENERGY

Inspection Date: 4/22/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06287 | Date: 4/22/2020

Inspection Photos



Photo 1. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06287 | Date: 4/22/2020

Inspection Photos



Photo 2. Facing northwest toward the location. Vegetation is well established in the interim reclamation area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06287 | Date: 4/22/2020

Inspection Photos



Photo 3. Facing toward the fill slope which is stabilized with vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06287 | Date: 4/22/2020

Inspection Photos



Photo 4. Facing toward the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06287 | Date: 4/22/2020

Inspection Photos



Photo 5. Well sign is posted at the well site. Emergency contact number on the sign needs to be updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06287 | Date: 4/22/2020

Inspection Photos



Photo 6. Facing northwest toward the cut slope. Vegetation is well established in the interim reclamation area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06287 | Date: 4/22/2020