

# Inspection Photos

API: 055-06209

Operator: TABULA RASA ENERGY

Inspection Date: 4/22/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06209 | Date: 4/22/2020

## Inspection Photos



**Photo 1.** Facing south toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06209 | Date: 4/22/2020



## Inspection Photos



**Photo 2.** Well sign is posted at the well head. Emergency contact number on the sign needs to be updated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06209 | Date: 4/22/2020



## Inspection Photos



**Photo 3.** Vegetation is well established along the fill slope. There is a lot of Native Rubber rabbit brush in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06209 | Date: 4/22/2020



## Inspection Photos



**Photo 4.** There is an erosion channel at the southeast side that will need to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06209 | Date: 4/22/2020



## Inspection Photos



**Photo 5.** Facing northwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06209 | Date: 4/22/2020