

# Inspection Photos

API: 055-06301

Operator: TABULA RASA ENERGY

Inspection Date: 4/22/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06301 | Date: 4/22/2020

## Inspection Photos



**Photo 1.** Facing north toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06301 | Date: 4/22/2020



## Inspection Photos



**Photo 2.** Vegetation is well established along the fill slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06301 | Date: 4/22/2020



## Inspection Photos



**Photo 3.** Well sign is posted at the well head. Emergency contact number on the sign needs to be updated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06301 | Date: 4/22/2020

## Inspection Photos



**Photo 4.** There is unused pipe being stored at the north side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06301 | Date: 4/22/2020



## Inspection Photos



**Photo 5.** The unused pipe at the location needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06301 | Date: 4/22/2020