

Inspection Photos  
Operator: Red Mesa  
API#: 067-06124  
Date: 4/23/2020



Photo 1. View of the project area from the well pad entrance facing center. Erosional channeling occurring from the access entrance and flowing southeastward.



Photo 2. View of dense Russian knapweeds within the eastern project area.




Photo 3. View of the southern project area from the southeastern corner facing westward. Plugged well marker in place.



Photo 4. View of musk thistles within the southern project area.



Photo 5. View of plugged well marker and remaining lines around plugged well location.



Photos 6-8. View of three separate access roads leading to well location.



Photo 9. View of dense kochia seedlings in an early growing condition at this time.



Photo 10. View of reference area vegetation comprised of open sagebrush shrubland with scattered juniper trees Grasses/herbs in the understory such as blue grama, sand dropseed and Indian ricegrass, penstemon spp. are observable in a dormant vegetative condition.