

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2020

Submitted Date:

04/27/2020

Document Number:

690005637

**FIELD INSPECTION FORM**

Loc ID 329226 Inspector Name: Carlile, Craig On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone | Email                         | Comment                         |
|---------------|-------|-------------------------------|---------------------------------|
| , Inspections |       | COGCCinspections@Anadarko.com | <a href="#">All Inspections</a> |

**General Comment:**

Large empty text area for general comments.

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                   |       |  |
|--------------------|-------------------|-------|--|
| Type               | IGNITOR/COMBUSTOR |       |  |
| Comment:           |                   |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | WELLHEAD          |       |  |
| Comment:           |                   |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | SEPARATOR         |       |  |
| Comment:           |                   |       |  |
| Corrective Action: |                   | Date: |  |

**Equipment:**

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| Type: Horizontal Heated Separator | # 1 |       | corrective date |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bird Protectors             | # 2 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Plunger Lift                | # 1 |       |                 |

|                               |     |       |  |
|-------------------------------|-----|-------|--|
| Comment:                      |     |       |  |
| Corrective Action:            |     | Date: |  |
| Type: Emission Control Device | # 1 |       |  |
| Comment:                      |     |       |  |
| Corrective Action:            |     | Date: |  |
| Type: Gas Meter Run           | # 1 |       |  |
| Comment:                      |     |       |  |
| Corrective Action:            |     | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type         | Tank ID | SE GPS |
|--------------------|---|----------|--------------|---------|--------|
| PRODUCED WATER     | 1 | OTHER    | PBV CONCRETE |         |        |
| Comment:           |   |          |              |         |        |
| Corrective Action: |   |          |              |         | Date:  |

Paint

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

Berms

| Type               | Capacity                    | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-----------------------------|---------------------|---------------------|-------------|
|                    |                             |                     |                     |             |
| Comment:           | Shared with crude oil tank. |                     |                     |             |
| Corrective Action: |                             |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 1 | 300 BBLs | STEEL AST |         | 40.199930,-104.702030 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

Paint

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|        |    |  |  |
|--------|----|--|--|
| Yes/No | NO |  |  |
|--------|----|--|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |                   |       |  |
|--------------------|-------------------|-------|--|
| Type               | Ignitor/Combustor |       |  |
| Comment:           |                   |       |  |
| Corrective Action: |                   | Date: |  |

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| <a href="#">Routine wellhead and battery inspecton.</a> | carlilec | 04/27/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 690005638    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5133291">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5133291</a> |