

Inspection Photos
Location Name: UPRR 43 PAN AM B#8
Location ID:318429



Photo 1 WH



Photo 2 loc pic with WH

Inspection Photos
Location Name: UPRR 43 PAN AM B#8
Location ID:318429



Photo 3 Electric panel for well



Photo 4 Location pic

Inspection Photos
Location Name: UPRR 43 PAN AM B#8
Location ID:318429



Photo 5 Loc pic



Photo 6 WH flow line not bull plugged or LOTO