

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2020

Submitted Date:

04/27/2020

Document Number:

693502726**FIELD INSPECTION FORM**Loc ID 318456 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Lara-Mesa,	303-825-4822	cogcc@kpk.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241327	WELL	PR	08/01/2017	OW	123-09116	UPRR 43 PAN AM I 24	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	Piles of dead weeds and wood on location		
Corrective Action:	Comply with rule 603 f	Date:	04/21/2020
Type	DEBRIS		
Comment:	Dead weeds around electric panel		
Corrective Action:	Comply with rule 603 f	Date:	04/21/2020

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Steel pipe		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	



**Inspected Facilities**Facility ID: 241327 Type: WELL API Number: 123-09116 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SI At time of inspection flowline valves off well head appear to be closedCorrective Action:  Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday April 27, 2020 at approximately 9:45AM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: UPRR 43 Pan AM I #24</p> <p>Operator: KP Kauffman</p> <p>API#: 05-123-09116</p> <p>County: Weld</p> <p>While there, I observed a well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Debris: Rule 603 f Corrective action date of 4-21-20 See photo 2</p> <p>Trash: Rule 603 f Corrective action date of 4-21-20 See photo 2</p> <p>This is a follow up inspection per Doc#693502677. At time of inspection corrective actions have not been addressed.</p> <p>Weather conditions: Clear and location dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of my inspection report.</p>	silverr	04/27/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693502727	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5133788">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5133788</a>