



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Gas meter run has not been calibrated see pic		
Corrective Action:	Measure gas per Rule 329	Date:	05/20/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares containment with oil tanks				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:				Date:	

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>	
Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 203696 Type: WELL API Number: 001-09256 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On 4/20/20 at approximately 1320 I, Inspector Justin Medina conducted an on-site inspection at KPK- API 001-09256 -Tippett ET AL 6-4 in Adams County Colorado. While there, I observed Producing well</p> <p>During this inspection the following possible compliance issues were observed:                      Gas meter run has not been calibrated see pic                      Measure gas per Rule 329. 5/20/20                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      At time of inspection perception of location may have been distorted due to weather conditions.                      This is a summary of inspection report.</p>	medinaj	04/20/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402376834	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5128834">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5128834</a>
699501106	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5128797">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5128797</a>