

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-10-69S98W /10NWNW

Location ID: 312654



Photo #1045 from entrance to location



Photo #1046 Tank capacity, contents and NFPA labels weathered and not legible.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-10-69S98W /10NWNW

Location ID: 312654



Photo #1047 Multiple places with debris on location.



Photo #1048 Multiple places with debris on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-10-69S98W /10NWNW

Location ID: 312654



Photo #1050 Multiple places with debris on location.



Photo #1049 Flow line riser not LO/TO.