

Inspection Photos

Location Name: MARALEX RESOURCES INC USA-69S98W /18NESW

Location ID: 312548



Photo #1051 from entrance to location



Photo #1052 Battery sign is weathered and not legible.

Inspection Photos

Location Name: MARALEX RESOURCES INC USA-69S98W /18NESW

Location ID: 312548



Photo #1053 Tank capacity, contents and NFPA label weathered and not legible.



Photo #1054 Multiple places with debris on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC USA-69S98W /18NESW

Location ID: 312548



Photo #1055 Multiple places with debris on location.



Photo #1056 Multiple places with debris on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC USA-69S98W /18NESW

Location ID: 312548



Photo #1057 Unused supplies and equipment.



Photo #1060 Tank berm has eroded.