

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-21-69S98W /21NENE

Location ID: 312648



Photo #1062 from entrance to location



Photo #1061 Lease road has not been maintained.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-21-69S98W /21NENE

Location ID: 312648



Photo #1064 Multiple places with debris on location.



Photo #1065 Multiple places with debris on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-21-69S98W /21NENE

Location ID: 312648



Photo #1066 Multiple places with debris on location.



Photo #1068 Tank has been disconnected.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-21-69S98W /21NENE

Location ID: 312648



Network: Apr 27, 2020 at 1:38:38 PM MDT
Local: Apr 27, 2020 at 1:38:38 PM MDT
+39.2643 -108.338



Network: Apr 27, 2020 at 1:39:02 PM MDT
Local: Apr 27, 2020 at 1:39:02 PM MDT
+39.2643 -108.338

Photo #1069

Photo #1070