

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-22-69S98W /22NENW

Location ID: 312650



Photo #1072 from entrance to location



Photo #1073 Lease road has not been maintained.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-22-69S98W /22NENW

Location ID: 312650



Photo #1076 Multiple places with unused equipment on location.



Photo #1077 Multiple places with unused equipment on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-22-69S98W /22NENW

Location ID: 312650



Photo #1074 Multiple places with debris on location



Photo #1075 Multiple places with debris on location