

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2020

Submitted Date:

04/27/2020

Document Number:

699800988

FIELD INSPECTION FORM

Loc ID 312548 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
14 Number of Comments
6 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 53255
 Name of Operator: MARALEX RESOURCES INC
 Address: P O BOX 338
 City: IGNACIO State: CO Zip: 81137

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	
Graves, Jim		mrinc20@maralexinc.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221891	WELL	PR	10/01/2019	GW	077-08493	USA 1-18 JC	PR

General Comment:

[COGCC Inspection Report Summary](#)
 On Monday 4/27/20 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC USA-69S98W /18NESW, Location #312654 in Mesa County Colorado.
 Refer to document #696600343 inspection conducted on 7/18/2019. Not all corrective actions have been completed.
 While there, I observed normal production operations.
 During this inspection the following possible compliance issues were observed: Battery sign is weathered and not legible. See photo #1052 with a corrective action date of 7/27/20. Tank capacity, contents and NFPA label weathered and not legible. See photo #1053 with a corrective action date of 7/27/20. Multiple places with debris on location. See photo #1054, #1055 and #1056 with a corrective action date of 5/11/20. Unused supplies and equipment. See photo #1057 with a corrective action date of 7/27/20. Tank berm has eroded. See photo #1060 with a corrective action date of 6/6/20. No pit permit on record for both pits. With a previous corrective action date of 8/5/19.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tank capacity, contents and NFPA label weathered and not legible. See photo #1053		
Corrective Action:	All tanks with a capacity of ten (10) barrels or greater shall be labeled with tank capacity, contents and NFPA label. Properly label tank.	Date:	07/27/2020
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign is weathered and not legible. See photo #1052		
Corrective Action:	Operators shall maintain signs in a legible condition, and shall replace damaged signs. Replace sign.	Date:	07/27/2020
Emergency Contact Number:			
Comment:	970-563-5000		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Multiple places with debris on location. See photo #1054, #1055 and #1056		
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove all debris from location.	Date:	05/11/2020
Type	STORAGE OF SUPL		
Comment:	Unused supplies and equipment. See photo #1057		
Corrective Action:	Production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove unused supplies from location.	Date:	07/27/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Pipe rail fence		
Corrective Action:		Date:	
Type	PIT		
Comment:	Netting		

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	STEEL AST		,
Comment:	Tank contents and capacity not legible.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Tank berm has eroded. See photo #1060			

Corrective Action:	Berms or other secondary containment devices shall be sufficiently impervious to contain any spilled or released material. Repair berm.	Date:	06/06/2020
--------------------	---	-------	------------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 221891 Type: WELL API Number: 077-08493 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Gravel						
Ditches						
		Ditches				
Berms						
Compaction						
		Gravel				
		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: _____ Lat: _____ Long: _____

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: No pit permit on record for both pits.

Corrective Action: Submit an eForm 15 Pit Report to update COGCC records with current information.

Date: 08/05/2019

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action:

Date: _____

Netting:

Netting Type: Mesh Netting Condition: Good

Comment:

Corrective Action:

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action:

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699800989	Photos for Insp. #699800988	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5134418