

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2020

Submitted Date:

04/27/2020

Document Number:

688307717

**FIELD INSPECTION FORM**

Loc ID 320672 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10646  
Name of Operator: AXIS EXPLORATION LLC  
Address: 370 17TH ST SUITE 5300  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Extraction	720-370-5540	COGCCInspections@extractionog.com	
Chesson, Robert		robert.chesson@state.co.us	
Dunning, Michael	303 396-6040	mdunning@extractionog.com	
Antonioli, Philip	720-345-4603	PAntonioli@extractionog.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150110	UIC DISPOSAL	AC	12/28/1983		-	REEVES 32-21 #4	TA

**General Comment:**

Inspection of excavation at decommissioned tank battery and no equipment remains at the tank battery. Injection well remains.

Remington on location to take confirmation samples, north and east sides are clean. Visual signs of hydrocarbon on west wall of excavation. Strong hydrocarbon smell coming from excavation. Hole is at least 30' deep.

Note: Operator is to schedule a time with inspector to do annual UIC visual pressures on injection well. With tank battery removed, well is now TA and a Form 4 is required for temporarily abandoned status of well

**Inspected Facilities**

Facility ID: 150110 Type: UIC API Number: - Status: AC Insp. Status: TA

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: _____
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: _____
			AnnMTReq: _____

Comment: Did not inspect well at this time.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Environmental**

**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other			
Comment	Excavation for E&P waste found while removing tank battery.			
Corrective Action				Date:

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688307721	Axis Exploration Reeves 32-12 4	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5134759">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5134759</a>