

Inspection Photos

API: 043-40002

Operator: JAVERNICK OIL

Inspection Date: 4/27/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-40002 | Date: 4/27/2020

Inspection Photos



Photo 1. Facing northwest along the access road. This portion of the road has been regraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40002 | Date: 4/27/2020

Inspection Photos



Photo 2. There are straw bales installed at culvert outlet however, this is not a long term BMP.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40002 | Date: 4/27/2020

Inspection Photos



Photo 3. Facing northwest at the access road. This portion of the access road has not been reclaimed. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40002 | Date: 4/27/2020

Inspection Photos



Photo 4. Facing west toward the location. The road circles the location and has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40002 | Date: 4/27/2020

Inspection Photos



Photo 5. This is the approximate location of the well. This area has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40002 | Date: 4/27/2020

Inspection Photos



Photo 6. There is cable and debris that remain at the north side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40002 | Date: 4/27/2020

Inspection Photos



Photo 7. Facing south at the location. The pipe and debris appear to have been removed from this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40002 | Date: 4/27/2020