

# Inspection Photos

API: 043-40006

Operator: JAVERNICK OIL

Inspection Date: 4/27/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-40006 | Date: 4/27/2020

## Inspection Photos



**Photo 1.** Facing southeast toward the location. There is cement debris that remains shown by red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40006 | Date: 4/27/2020



## Inspection Photos



**Photo 2.** Facing south where well was located. This area is bare of vegetation and must be reclaimed. There is various debris along the ground.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40006 | Date: 4/27/2020



## Inspection Photos



**Photo 3.** There are cement block and cemented anchor that remain at the south side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40006 | Date: 4/27/2020



## Inspection Photos



**Photo 4.** The access road made a circle around the well site. There is still gravel that remains and areas bare of vegetation along the former access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40006 | Date: 4/27/2020



## Inspection Photos



**Photo 5.** Facing northwest where well was located. This area is bare of vegetation and must be reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40006 | Date: 4/27/2020