

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2020

Submitted Date:

04/28/2020

Document Number:

699301560**FIELD INSPECTION FORM**Loc ID 318137 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240691	WELL	PR	07/01/2019	OW	123-08479	JOHNSON 1	PR

General Comment:

Location				
Lease Road:				
Type	Access			
comment:	rutted needs work			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:	Adequate			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Adequate			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Adequate			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Mechanical issue packing around tubing is leaking			
Corrective Action:	Comply with Rule 605.d			Date: 01/24/2020
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	steel pipe and hog fence roll			
Corrective Action:				Date:
Equipment:				
Type: Bradenhead	# 1			corrective date
Comment:	exposed at surface			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	electric panel, transformers and meter box.			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	50 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Inspected Facilities

Facility ID: 240691 Type: WELL API Number: 123-08479 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 4/28/2020 at approximately 1235 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Johnson #1 at API #05-123-08479 in Weld County Colorado.</p> <p>While there, I observed Producing wellsite, this is a follow up inspection per Doc. # 699300878</p> <p>During this inspection the following compliance issue has been addressed:</p> <p>210.e Signs: WH sign is faded & emergency # is not legible, see attached photo 1.</p> <p>During this inspection the following possible compliance issue was observed and is now delinquent:</p> <p>605.d Mech. Issue: Hammer union around WH packing appears to be loose and leaking around tubing CA date 1-24-2020 see attached video.</p> <p>Location is dry, weather is clear.</p> <p>I called the emergency number @ 1241 hrs and spoke with Hannah the secretary for KP Kauffman explained to her that the packing around the tubing was leaking that I had been out in January and reported it then , she said she would relay the message to the lease operator and get it fixed .</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	04/28/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301562	leak vid	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5135605
699301563	locaton pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5135606