

Location			
Lease Road:			
Type	Access		
comment:	in crop		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 292937 Type: WELL API Number: 123-26421 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
This is a follow up inspection to previous inspection DOC#: 679601912. All corrective actions assigned in previous inspection DOC#: 679601912 has been resolved. No new corrective actions were observed at the time of re-inspection. Review my inspection, photos and previous inspection DOC#: 679601912 for additional information on this location. **Weather Conditions: sunny, dry ground, windy	santistb	04/28/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679602547	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5135592